

IBC™ Brand Cleaner Z1125 Instruction Manual

Thank you for choosing the IBC™ Brand Cleaner Z1125. The IBC™ Brand Cleaner Z1125 is a high-performance device designed for cleaning the ferrule end faces of LC connectors and MU connectors. Carefully read this instruction manual before using this device. Please keep this instruction manual for future reference.

1. Safety precautions

	Though our device is deemed safe, improper usage or handling can still inflict injury to others. IBC Brand Cleaner Z1125 is designed to clean LC connectors and MU connectors only. US Conec is not liable for damage caused in attempt to apply this device to other applications.
---	--

2. Notes on usage

Do not attempt to disassemble as this can cause damage to the device.

Do not re-use cleaning cloth as this will eliminate its cleaning ability.

Do not touch the cleaning cloth as this will cause contamination.

Do not pull the cleaning cloth, use only the device body.

Do not use this cleaner when the cloth is empty, as this can cause damage to the connector.

3. Notes on storage for extended periods


Do not expose device to direct sunlight, high temperature or high humidity.

The cover on the guide cap should be closed at all times when device is not in use.

4. Sales enquiries

US Conec Ltd.
 Tel : 828-323-8883 Fax : 828-326-8808 Toll Free : 800-769-0944
 E-mail : customerservice@usconec.com
 Website : <http://www.usconec.com>



5. Device construction



No.	Part Name	Function
A	Tip	Lead the cleaning cloth to the optical connector end face.
B	Nozzle	Lead tip to the optical connector end face.
C	Outer Shell	Push the outer shell to clean the connector.
D	Guide Cap	Acts as dust cap or cleaning adaptor for connector plug.
E	Indicator	Provides indication of remaining cleaning cloth.
F	Guide Cap Holder	The guide cap can be fixed to a fixed part.
G	Retractable Lanyard	Operator can keep the product in the pocket by this lanyard.


6. Applications

<Connector inside adaptor>

1. Remove Guide Cap from the device

2. Insert tip of cleaner into MU/LC Adaptor


Note: This drawing shows only LC, but this product can clean MU too.

3. Push the Outer Shell to start cleaning the MU/LC connector end face. A "click" sound indicates end of cleaning process. Close the cover after use.





Be careful not to slant the IBC Brand Cleaner Z1125 while inserting into the adaptor.

Do not overly exert force during insertion as this may cause damage to both the connector and the IBC Brand Cleaner Z1125.


If pushing Outer Shell is inhibited, remove IBC Brand Cleaner Z1125 from adaptor and ensure that there is no sizeable debris inhibiting the cleaning process.

<Connector plugs alone>

1. Open the Cover on the Guide Cap

2. Insert MU/LC connector into the Guide Cap


Note: This drawing shows only LC, but this product can clean MU too.

3. Push the Outer Shell to start cleaning the MU/LC connector end face. A "click" sound indicates end of cleaning process. Close the cover after use.



Do not overly exert force during insertion as this may cause damage to both the connector and the IBC Brand Cleaner Z1125.

If pushing Outer Shell is inhibited, remove IBC Brand Cleaner Z1125 from adaptor and ensure that there is no sizeable debris inhibiting the cleaning process.