

HDMI to DP Converter

User Manual



Contents

1.0 INTRODUCTION	1
2.0 FEATURES	1
3.0 SPECIFICATIONS	1
4.0 PACKAGE CONTENTS	2
5.0 OPERATION	2
6.0 CONNECTION DIAGRAM.....	2

HDMI to DP Converter

DEAR CUSTOMER

Thank you for purchasing this product. For optimum performance and safety, please read these instructions carefully before connecting, operating or using this product. Please keep this manual for future reference.

1.0 INTRODUCTION

This Adapter fully converts HDMI signal into standard DisplayPort signal. It perfectly connects different source devices to DisplayPort Displays by using the provided conversion cables

2.0 FEATURES

- Support HDMI input, DisplayPort 1.1a output
- Supports HDMI resolution of max up to 1080p
- Support DP resolution up to 1920x1200
- Supports HDMI uncompressed 2 channel audio such as LPCM.
- Storing EDID information on the converter to make sure that there is a better compatibility between the source and display
- Video Pass-Through, not scaling

3.0 SPECIFICATIONS

Input/Output Connector	
Input	HDMI
Output	DisplayPort
Resolution	
HDMI	1080P(MAX)
DisplayPort	1920x1200(MAX)

Warranty	
Limited Warranty	1 Year
Environmental	
Operating Temperature	0 °C to +45°C
Operating Humidity	10% to 85 % RH (no condensation)
Storage Temperature	-10°C to +70°C
Storage Humidity	5% to 90 % RH (no condensation)
Power Requirement	
Power Consumption (Max)	3.8W (5V/765mA)
Power Source	External AC Adapter
Power Supply	10W (5V/2A)
Accessories Adapter	
User Manual	English Version

4.0 PACKAGE CONTENTS

Before attempting to use this unit, please check the packaging and make sure the following items are contained in the shipping carton:

- Main unit x1
- User Manual x1
- 5V/2A Power Supply

5.0 OPERATION

- 1) Connect the input port to an HDMI source via an HDMI cable
- 2) Connect the output port to a DP display via a DP Cable

6.0 CONNECTION DIAGRAM

