

Compaq Evo Series; N110 , N150, N200,N400c, N410c, N600c,N610c, N620c, N800, N800c, N800v,N800w; Compaq Armada Series;110,110s, E300,E500,E500s,E700,M300, M500,M700,V300; Compaq Presario 900,1700, ZZ00, Z800, B1000,B2000,B3000, M2000, V1000, V2000, V2100,V2200,V2300, V2400, VZ500, V2600, VZ700,V3000,V3100, V3300, V3300, V3400, V3500,V3600,V4000,V6000, V6100, V6200, V6300,V6400,V6500Series;

HP Pavillion DV1000,DV1100, DV1200, DV1300, DV1400, DV1500, DV1600, DV1700, DV2000, DV2100, DV4000, DV6000, DV6100、DV6500、DV6600, DV8000, DV8200, DV8300, DV9000, DV9100, DV9200, DV9300, DV9400. DV9500, DV9600, DV9700, DV9800, DV9900, DX6600 Series

ZT3000, ZT3200, ZT3300, HP Compaq ZE2000, ZE2100, ZE2200.ZE2300,ZE2400,X1000,X1100,X1200, X1300, X1400, X1500 Series

Tablet PC TC1000,TC1100, MZ000,TC4Z00 series;

Business, Notebook nc4000, nc4010, nc4Z00, nc6000,nx6110, nc6120, nc6ZZ0, ix6Z30, nc8000, nc8230,nw8000,nwBZ00, nw8240,nx5000,nx6110,nx6125, nx7000,nx7010 ,nx8220,nx9000, nx9020.nx9030,nx9040 series